

TAMPERTECH Teaches:


What is Surface energy?

Tamper evident tapes and labels are only as effective as the surface they are applied to.

Many factors can influence how well a tape or label will stick to a surface; roughness, smoothness, porosity, coated, uncoated, cleanliness, flexibility, temperature conditions, wet or dry, and finally, surface energy of the surface.

Materials with a low surface energy are harder to stick too so to make sure our products will work their best how can you test surface energy!

This test allows us to ensure that we can provide the best possible product to meet your needs.



If you have any other questions do get in touch!